

multimeter YX1000A (MF110)

Общее описание

- Ручной выбор пределов измерений
- Большой стрелочный индикатор
- Измерение в dB: -20dB ~ 56dB



| | | | |
|---|-------|---|----------------|
| | | | |
| | max | | |
| | 1 | | ±5% |
| | 1 | | ±5% |
| | 250 A | | ±5% |
| | | - | - |
| | 200 | | ±5% |
| | | | |
| : | | | |
| : | | | |
| : | | | |
| | | | |
| | p-n | : | |
| : | | | |
| : | | | |
| : | | | |
| : | | | |
| : | | | |
| : | | | |
| | | | |
| : | | | |
| : | | | |
| : | | | |
| : | | | 1,5 |
| : | | | 90 x 60 x 30 . |
| : | | | 110 . |
| : | | | |
| : | | | |
| : | | | |